



Wuhan Fengfan Electroplating International Trading Co., Ltd.

3F, No.8 LingJiaoHu Rd., Hankou, Wuhan 430015, China
Tel: 86-27-85615818 Fax: 86-27-85615828
www.fengfantrade.net

ZN-638

Brightener for Potassium Chloride Zinc Plating

Plating Process

TECHNICAL DATA

ZN-638

ZN-638 brightener for potassium chloride plating of zinc

- It is our new generation potassium salt zinc plating brightener, its performance is same to similar products overseas.
- There are two agents, brightener and MU. It is white-bright and fast-gloring.
- Excellent at anti-Ferrous impurity, for both barrel and rack operations
- Subtle layer, good luster, easily to yellowish-passivation, blue and white passivation, white-passivation.
- Stable solution, less consumption, wide temp-range, high cloud point, suitable to produce at high temp

1. TECHNICAL FORMULA

Formula and Operation Condition	Rack plating	Barrel plating
KCl	180~220g/L	200~240g/L
ZnCl ₂	60~70g/L	40~55g/L
H ₃ BO ₃	30~35g/L	30~35g/L
ZN-638A Brightener	0.3~1ml/L	0.2-1 ml/L
ZN-638B MU	15-25ml/L	15-25 ml/L
PH	4.5~5.5	5.0~6.0

DK	0.5~5A/dm ²	0.2~3A/dm ²
SK : SA	1 : 1.5~2	1 : 1.5~2
Anode	0#zinc plate	0#zinc plate

2. Bath Preparation

- 1) Add water at the 2/3 amount of bath volume, then add above amount of KCl and ZnCl₂ and stir.
- 2) Dissolve H₃BO₃ with 80°C hot water and add slowly into the bath, then add 1-2g/L zinc powder. Stir 20-30 minutes.
- 3) Filter into the bath after solution becomes clarified. Add water according to calculated volume.
- 4) Dissolve above calculated Zn-638 additive by one time of volume water and add into the bath. Stir uniform, and then start to do trial plating.

3. Bath Management

- 1) ZN—638A brightener consumption is 100--150ml/KAh, ZN—638B MU consumption is 80~100ml/KAh.
- 2) When adding brightener, mix brightener and MU at the ratio of 1-2 to 1 volume uniform, dissolve with water at 1 or 2 times, and then add into the bath. Add less but more times.
- 3) If the previous solution is KCl zinc plating, do not need any special treatment, add Zn-638 directly.
- 4) When adjust and reduce PH value, dilute HCl at 5-10 times water and then use.
- 5) Guarantee bath solution stable when producing, dissolve raw material out of the bath before replenishing.

4. Trouble-shooting

Phenomenon	Cause	Action
Turbid solution, more consumption brightener	<ol style="list-style-type: none"> 1. Too much Fe impurity 2. Too much solid 3. pH value too high or too low 4. Temp too high 5. KCl assay too high 6. Pretreatment not good 	<ol style="list-style-type: none"> 1. Add WZn acid zinc plating impurities remover or treat 2. Filter 3. Adjust to normal range 4. Reduce temp 5. Adjust to normal range 6. Strengthen pre-treatment
Not good covering power	<ol style="list-style-type: none"> 1. Not sufficient brightener 2. Low KCl assay, High ZnCl₂ 	<ol style="list-style-type: none"> 1. Replenish brightener appropriately

	<p>assay</p> <ol style="list-style-type: none"> 3. Too low or too high pH value 4. Too high temp 5. Too low current density 	<ol style="list-style-type: none"> 2. Analysis and adjust 3. Adjust to normal range 4. Reduce temp to normal range 5. Raise current density
Scorch easily, barrel Mark, less brightness	<ol style="list-style-type: none"> 1. Too high Fe impurity 2. Too high current 3. Too high or too low pH value 4. Less H₃BO₃ 	<ol style="list-style-type: none"> 1. Add WZn acid zinc plating impurities remover 2. Reduce current density 3. Adjust to normal range 4. Add proper H₃BO₃
Not good plating in low current region after replenish KCl, ZnCl ₂	<ol style="list-style-type: none"> 1. Drag into Fe impurity 2. Drag into Cu and Pb impurity 3. Not sufficient brightener 	<ol style="list-style-type: none"> 1. Electrolyte with low current or add WZn impurities remover 2. Electrolyte with low current or treat by zinc powder 3. Replenish proper brightener
Not bright, foggy layer	<ol style="list-style-type: none"> 1. Not sufficient brightener 2. Too much organic impurities 3. Too much metal impurities 	<ol style="list-style-type: none"> 1. Replenish appropriately 2. Big treatment 3. Big treatment or add WZn impurities remover
Blistered, Peeled, Blackened layer	<ol style="list-style-type: none"> 1. Not good pre-treatment 2. Add too much or too less brightener or MU. 	<ol style="list-style-type: none"> 1. Do pre-treatment well 2. Absorb with activated charcoal and adjust

Declaration: All about these product suggestions are based on our trust test and data, for reference only.